cole

03500.014088.1

PATENT

	611	06 ²	4708 106) y,
1	No. of	MDEM	În 1	/ re Pa

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
TAIKO MOTO	DI ET AL.	:	Examiner: D. Dong
Appln. No.: 1	0/086,334	:	Group Art Unit: 2879
Filed: March	4, 2002	:)	Certificate
	CTRON-EMITTING DEVICE CTRON SOURCE USING THE) :	FEB 2 4 2006
	TRON-EMITTING DEVICES, IMAGE-FORMING APPARATUS) :	of Correction
USIN	G THE ELECTRON SOURCE)	
U.S. Patent No	.: 6,888,296 B2)	
Issued: May	3, 2005)	February 3, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

LETTER CALLING ATTENTION TO ERRORS IN PATENT

Sir:

The following minor errors have been noted in the above-mentioned patent:

ON THE TITLE PAGE [56] REFERENCES CITED:

Foreign Patent Documents, "07065703 3/1995" should read --7-065703 3/1995--.

COLUMN 3:

Line 26, "large" should read --largely--.

COLUMN 15:

Line 34, "was" should be deleted.

COLUMN 16:

Line 24, "is" should read --has--.

COLUMN 26:

Line 45, "values;" should read --values:--.

COLUMN 28:

Line 47, "values;" should read --values:--.

COLUMN 30:

Line 19, "values;" should read --values:--.

COLUMN 32:

Line 28, "values;" should read --values:--.

COLUMN 38:

Line 28, "values;" should read --values:--.

COLUMN 40:

Line 41, "values;" should read --values:--.

These errors appear to be relatively insignificant and, therefore, we do not believe it is necessary to request a Certificate of Correction. However, it is requested that this paper be placed in the filewrapper of the above-identified patent.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank DeLucia

Attorney for Patentees Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_MAIN 518448v1